



REPORT 160095R1

Revision 0

Patrick Port Botany Terminal Biannual Environmental Noise Compliance Monitoring May 2018

PREPARED FOR:
Patrick Port Botany Terminal
PO Box 197
Botany NSW 1455

29 May 2018



Patrick Port Botany Terminal Biannual Environmental Noise Compliance Monitoring May 2018

PREPARED BY:

Rodney Stevens Acoustics Pty Ltd

Telephone: 61 2 9943 5057 Facsimile 61 2 9475 1019 Email: info@rodneystevensacoustics.com.au Web: www.rodneystevensacoustics.com.au

DISCLAIMER

Reports produced by Rodney Stevens Acoustics Pty Ltd are prepared for a particular Client's objective and are based on a specific scope, conditions and limitations, as agreed between Rodney Stevens Acoustics and the Client. Information and/or report(s) prepared by Rodney Stevens Acoustics may not be suitable for uses other than the original intended objective. No parties other than the Client should use any information and/or report(s) without first conferring with Rodney Stevens Acoustics.

The information and/or report(s) prepared by Rodney Stevens Acoustics should not be reproduced, presented or reviewed except in full. Before passing on to a third party any information and/or report(s) prepared by Rodney Stevens Acoustics, the Client is to fully inform the third party of the objective and scope and any limitations and conditions, including any other relevant information which applies to the material prepared by Rodney Stevens Acoustics. It is the responsibility of any third party to confirm whether information and/or report(s) prepared for others by Rodney Stevens Acoustics are suitable for their specific objectives.

DOCUMENT CONTROL


Reference	Status	Date	Prepared	Checked	Authorised
160095R1	Revision 0	29 May 2018	Thomas Carney	Desmond Raymond	Rodney Stevens




Appendix B – Unattended Logger Results – Chelmsford Avenue


34 Chelmsford Ave, Botany





























































Appendix C – Unattended Logger Results – Dent Street


26 Dent St, Botany




























































Appendix D - Unattended Logger Results - Botany Road


1424 Botany Rd, Botany


























































Appendix E - Unattended Logger Results - Australia Avenue

80 Australia Ave, Matraville

